
UNITED	STATES	PUBLIC	LAND	SURVEY	CORNER	CERTIFICATE
			O	F		

Land Survey Monuments situated in Section, Tow, Tow	vnship <u>74N</u> , Range
Previously recorded in Book 2, Page 145 ir	n the County Recorder's Office
(book, page, document number,etc.)	3, 11, 12, 12, 12, 12, 13, 13, 13, 13, 13, 13, 13, 13, 13, 13
(Show reason for preparing this certificate, the evidence and detailed procedures used monumentation found or placed.)	in establishing the corner positions and
Monument Description and Remarks: Found 4" x 4" WPA concrete mostone on north side and 1-1/2" iron pipe on east side. Previous ties altered	
This Corner was used for a Plat of Survey in the SW 1/4 of the SE 1/4 of Se 2713.	ec. 25, recorded in Bk. 2015, P.

PLAN VIEW


(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SW Corner, SW 1/4 of the SE 1/4, Section 25

Date of Survey: 6/6/15

NOTE: ALL TIES TO BRASS DISK OR YELLOW/ORANGE SURVEY MARKER UNLESS NOTED.



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly Licensed Land Surveyor under the laws of the state of lowa.

Signature: J. Brian Morrissey

License number 7995.

My license renewal date is December 31, 2015

806-15-3/6

